



**Tabla de conversión:
°C a °F**

1°C = 1,80°F		3°C = 5,40°F		5°C = 9,00°F		7°C = 12,60°F		9°C = 16,20°F	
2°C = 3,60°F		4°C = 7,20°F		6°C = 10,80°F		8°C = 14,40°F		10°C = 18,00°F	
°C = °F		°C = °F		°C = °F		°C = °F		°C = °F	
-250	-418,00	41	105,80	101	213,80	161	321,80	410	770
-200	-328,00	42	107,60	102	215,60	162	323,60	420	788
-150	-238,00	43	109,40	103	217,40	163	325,40	430	806
-100	-148,00	44	111,20	104	219,20	164	327,20	440	824
-50	-58,00	45	113,00	105	221,00	165	329,00	450	842
-40	-40,00	46	114,80	106	222,80	166	330,80	460	860
-30	-22,00	47	116,60	107	224,60	167	332,60	470	878
-20	-4,00	48	118,40	108	226,40	168	334,40	480	896
-17,78	0,00	49	120,20	109	228,20	169	336,20	490	914
-12	10,40	50	122,00	110	230,00	170	338,00	500	932
-10	14,00	51	123,80	111	231,80	171	339,80	550	1022
-8	17,60	52	125,60	112	233,60	172	341,60	600	1112
-7	19,40	53	127,40	113	235,40	173	343,40	650	1202
-6	21,20	54	129,20	114	237,20	174	345,20	700	1292
-5	23,00	55	131,00	115	239,00	175	347,00	750	1382
-4	24,80	56	132,80	116	240,80	176	348,80	800	1472
-3	26,60	57	134,60	117	242,60	177	350,60	850	1562
-2	28,40	58	136,40	118	244,40	178	352,40	900	1652
-1	30,20	59	138,20	119	246,20	179	354,20	950	1742
0	32,00	60	140,00	120	248,00	180	356,00	1000	1832
1	33,80	61	141,80	121	249,80	181	357,80	1050	1928
2	35,60	62	143,60	122	251,60	182	359,60	1100	2012
3	37,40	63	145,40	123	253,40	183	361,40	1150	2102
4	39,20	64	147,20	124	255,20	184	363,20	1200	2192
5	41,00	65	149,00	125	257,00	185	365,00	1250	2282
6	42,80	66	150,80	126	258,80	186	366,80	1300	2372
7	44,60	67	152,60	127	260,60	187	368,60	1350	2462
8	46,40	68	154,40	128	262,40	188	370,40	1400	2552
9	48,20	69	156,20	129	264,20	189	372,20	1450	2642
10	50,00	70	158,00	130	266,00	190	374,00	1500	2732
11	51,80	71	159,80	131	267,80	191	375,80	1550	2822
12	53,60	72	161,60	132	269,60	192	377,60	1600	2912
13	55,40	73	163,40	133	271,40	193	379,40	1700	3092
14	57,20	74	165,20	134	273,20	194	381,20	1800	3272
15	59,00	75	167,00	135	275,00	195	383,00	1900	3452
16	60,80	76	168,80	136	276,80	196	384,80	2000	3632
17	62,60	77	170,60	137	278,60	197	386,60	2100	3812
18	64,40	78	172,40	138	280,40	198	388,40	2200	3992
19	66,20	79	174,20	139	282,20	199	390,20	2300	4172
20	68,00	80	176,00	140	284,00	200	392	2400	4352
21	69,80	81	177,80	141	285,80	210	410	2500	4532
22	71,60	82	179,60	142	287,60	220	428	2600	4712
23	73,40	83	181,40	143	289,40	230	446	2700	4892
24	75,20	84	183,20	144	291,20	240	464	2800	5072
25	77,00	85	185,00	145	293,00	250	482	2900	5252
26	78,00	86	186,80	146	294,80	260	500	3000	5432
27	80,60	87	188,60	147	296,60	270	518	3100	5612
28	82,40	88	190,40	148	298,40	280	536	3200	5792
29	84,20	89	192,20	149	300,20	290	554	3300	5972
30	86,00	90	194,00	150	302,00	300	572	3400	6152
31	87,80	91	195,80	151	303,80	310	590	3500	6332
32	89,60	92	197,60	152	305,60	320	608	3600	6512
33	91,40	93	199,40	153	307,40	330	626	3700	6692
34	93,20	94	201,20	154	309,20	340	644	3800	6872
35	95,00	95	203,00	155	311,00	350	662	3900	7052
36	96,80	96	204,80	156	312,80	360	680	4000	7232
37	98,60	97	206,60	157	314,60	370	698	4250	7682
38	100,40	98	208,40	158	316,20	380	716	4500	8132
39	102,20	99	210,20	159	318,20	390	734	4750	8582
40	104,00	100	212,00	160	320,00	400	752	5000	9032

Aplicación: 10°C a °F

$$10 \times 1,80 + 32 = 50°F$$

4225°C a °F

$$4225 \times 1,80 + 32 = 7637°F$$

589°C a °F

$$589 \times 1,80 + 32 = 1092,20°F$$

NOTA: Para esta conversión °C a °F siempre se sumará el diferencial entre las dos escalas, es decir 32°F